


Frame 1 AC Electric Winch

Parts Breakdown



Parts List

WD2000-1A34-F-02

Item	Part Number	Qty.	Description	Item	Part Number	Qty.	Description
1	34K842-0068G1	1	Motor	21	27337	1	Gear Housing
2	32240	1	Coupling	22	-----	10	#10-24 X 2-1/4" SHCS
3	31610	1	Drum Support	23	68611	1	Freespool lever
4	13831	1	Drum Bushing	24	13872	1	Clutch Retainer
5	-----	4	1/4-20 X 1" SHCS	25	MC1213	1	Full Voltage Pendant
6	13799	1	Drum brake				
7	26107	1	Drum				
8	32408	2	Tie Rod				
9	-----	4	5/16-18 X 1" SHCS				
10	34506	1	Drum Support				
11	-----	1	5/16" X 11.49" hex shaft				
12	13848	2	Gasket				
13	25308	1	Ring Gear				
14	14584	1	Planetary Gear Coupler				
15	28432	1	3rd Stage Carrier				
16	13826	1	Nylon Thrust Washer				
17	28431	1	2nd Stage Carrier				
18	28430	1	1st Stage Carrier				
19	13874	1	Sun Gear				
20	28353	1	Sliding Ring Gear				