


Frame 2 Pneumatic Winch

Parts Breakdown



Parts List

WF3150-P-02

Item	Part Number	Qty.	Description
1	VA6CXXX10	1	Pneumatic Motor
2	-----	10	1/4-20 x 1-1/4" SHCS
3	MC1065	1	Motor Adapter
4	-----	4	3/8-16 x 3/4" SHCS
5	-----	6	3/8-16 x 1-1/4" SHCS
6	14964	3	Gasket
7	31675	2	Drum Support
8	30274	2	Drum Bushing
9	30275	2	Seal
10	30277	2	Thrust Washer
11	MC1011	1	Coupler
12	30268	3	Tie Rod
13	31683	1	Drum Brake
14	31671	1	Drum
15	36974	1	Set Screw
16	31672	1	Bearing/Tolerance Ring
17	3000-X187	1	Snap Ring
18	30329	1	Drive Shaft Adapter
19	30314	1	Drive Shaft
20	30310	1	3rd Stage Carrier

Item	Part Number	Qty.	Description
21	18598	1	2nd Stage Carrier
22	15581	2	Retaining Ring
23	15654	1	1st Stage Carrier
24	34837	1	Clutch Gear
25	19574	1	Sun Gear
26	64252	1	Thrust Plug
--	36634	1	Clutch Retainer
28	39928	1	Freespool Lever
29	31676	1	Gear Housing Assembly
30	-----	10	1/4-20 x 1-1/4" SHCS
31	MC1057	1	Spacer