


Frame 2 Pneumatic Winch

Parts Breakdown



Parts List

WF3150-P-03

Item	Part Number	Qty.	Description	Item	Part Number	Qty.	Description
1	VA6CXXX10	1	Pneumatic Motor	21	18598	1	2nd Stage Carrier
2	-----	10	1/4-20 x 1-1/4" SHCS	22	15581	2	Retaining Ring
3	MC1065	1	Motor Adapter	23	15654	1	1st Stage Carrier
4	-----	4	3/8-16 x 3/4" SHCS	24	34837	1	Clutch Gear
5	-----	6	3/8-16 x 1-1/4" SHCS	25	19574	1	Sun Gear
6	14964	3	Gasket	26	64252	1	Thrust Plug
7	31675	2	Drum Support	--	36634	1	Clutch Retainer
8	30274	2	Drum Bushing	28	39928	1	Freespool Lever
9	30275	2	Seal	29	31676	1	Gear Housing Assembly
10	30277	2	Thrust Washer	30	-----	10	1/4-20 x 1-1/4" SHCS
11	MC1011	1	Coupler	31	MC1057	1	Spacer
12	31288	3	Tie Rod				
13	-----	1	Drum Brake				
14	32225	1	Drum				
15	36974	1	Set Screw				
16	31672	1	Bearing/Tolerance Ring				
17	3000-X187	1	Snap Ring				
18	30329	1	Drive Shaft Adapter				
19	30314	1	Drive Shaft				
20	30310	1	3rd Stage Carrier				