


Frame 2 AC Electric Winch

Parts Breakdown



Parts List

WF7000-2A34-L-03 (3Ø)

Item	Part Number	Qty.	Description	Item	Part Number	Qty.	Description
1	VM3559	1	AC Electric Motor	21	30310	1	3rd Stage Carrier
2	-----	10	1/4-20 x 1-1/4" SHCS	22	18598	1	2nd Stage Carrier
3	MC1057	1	Spacer	23	15581	2	Retaining Ring
4	MC1065	1	Motor Adapter	24	15654	1	1st Stage Carrier
5	-----	4	3/8-16 x 3/4" SHCS	25	34837	1	Clutch Gear
6	-----	6	3/8-16 x 1-1/4" SHCS	26	19574	1	Sun Gear
7	14964	2	Gasket	27	64252	1	Thrust Plug
8	31675	2	Drum Support	28	36634	1	Clutch Retainer
9	30274	2	Drum Bushing	29	39928	1	Freespool Lever
10	30275	2	Seal	30	31676	1	Gear Housing Assembly
11	30277	2	Thrust Washer	31	-----	10	1/4-20 x 1-1/4" SHCS
12	MC1011	1	Coupler	32	MC1048	1	Control Box
13	31288	3	Tie Rod	33	MC1230	1	Low-Voltage Pendant
14	-----	1	Drum Brake				
15	32225	1	Drum				
16	36974	1	Set Screw				
17	31672	1	Bearing/Tolerance Ring				
18	3000-X187	1	Snap Ring				
19	30329	1	Drive Shaft Adapter				
20	30314	1	Drive Shaft				